

Bobcat in behind a log cradle cleaning up (unauthorized area)...Wagner comes to pick up logs...Wagner tusks spear cab and begins to crush it with operator inside...operator has no radio to contact Wagner to stop...an employee nearby sees this and stops the Wagner...a serious near miss.



