

Date:	March 31, 2010	<input type="checkbox"/> Close Call	<input checked="" type="checkbox"/> Incident
Title of Hazard Alert	Log turner – crush - lockout		
Intended for Review By	All departments		
Division	Soda Creek		

HAZARD ALERT

Incident Summary

On March 26th, a millwright was working on a v-flight conveyor. The chain broke and was being reconnected. The chain was piled up on the tail end of the conveyor at the entrance to the log turner. The millwright reached past the conveyor and into the log turner to free up the hung up chain. The framework for the log turner rolls pivoted open squeezing the worker between the frame work and the conveyor trough.

The v-flight conveyor was locked out. Energy sources upstream and downstream were improperly locked out.

Corrective Actions: Guarding was installed to prevent entry, Moving parts in facility are identified by color, Review use of main disconnects, Review SWP and lockout policy for clarity, Educate/crew talk on locking out energy sources up/down stream and above/below work area.

Occupation: Millwright

Injury: Broken shoulder blade

Years with employer: 30 years

Years on the job: 7 years

Worker was here

